

Amendments to the Specification:

At page 5, lines 19-25 please delete the text and replace with the following:

In Fig.6, a tangential bypass motor-fan unit 400 has a tangential exhaust port 402 extending from the fan assembly 403 which is covered with noise suppression sleeve 404, made of the V-0 Foam. Sleeve ~~[[304]]~~ 404 does not provide a sleeve cover, but rather is open at end 406. Sidewall 408 preferably abuts the outer surface of exhaust port 40, as generally shown. Extending from an interior surface of the sleeve may be internal flanges 408 that form a labyrinth flow path 410. The path 410 re-directs the air flow and the flanges effectively “scramble” or muffle the noise generated by the unit 400.